Facility Services Contracts Provided for Information Only (over \$50,000 and up to \$500,000)

#	User/Budget Holder School/Dept.	Products/Services Details	Ward	Recommended Supplier	Low Bid / Highest Score	Object- ions	No. of Bids Rec'd	Total Contract Amount	Projected Start/End Date of Contract	Customer Involvement	Funding Source
				R	OOFING						
1	Design and Renewal	PCM23-560T Mill Valley Jr. School TR 22-1383 Roof Replacement. Existing roof assemblies are deteriorated, exceeded its useful lifespan, and require full roof assembly replacement for roofs A3, C, C1, C2 and metal roof restoration for roof A1A.	2	Dufferin Roofing Ltd.	Yes	No	5	\$265,000	April 2023/ August 20, 2023	Design and Renewal	School Condition Improvement
2	Design and Renewal	MP23-542T Greenholme JMS TR-22- 0077 Restore Canopy @ Exits 3 & 4. Existing canopy roofs have exceeded their useful lifespan and require replacement. Painting of columns is required.	1	Dufferin Roofing Ltd.	Yes	No	5	\$63,100	April 2023/ August 25, 2023	Design and Renewal	School Condition Improvement
				MEG	CHANICAL						
3	Design and Renewal	PCM23-522T Heritage Park TR 22- 0440 Generator Replacement. Existing old diesel generator was found to be non-TSSA compliant. New generator is to be natural gas.	22	Gorbern Mechanical Contractors Ltd.	Yes	No	4	\$406,480	March 2023/ August 30, 2023	Design and Renewal	School Condition Improvement
4	Design and Renewal	PCM23-549P Burnhamthorpe CI TR- 22-0309 Professional Services, Steam to Hot Water (HW) Conversion & Air Handling Unit (AHU) Replacement.	2	GPY + Associates Engineering Inc.	Yes	No	4	\$208,480	April 2023/ August 4, 2023	Design and Renewal	School Condition Improvement
5	Design and Renewal	VK23-581P Agincourt CI TR-23-0345 Professional Services, Replacement of Heating Plant, Air Handling Units, Unit Ventilators and Building Automation System (BAS).	21	GPY + Associates Engineering Inc.	Yes	No	5	\$102,800	April 2023/ July 24, 2023	Design and Renewal	School Condition Improvement
6	Design and Renewal	PCM23-480P Ryerson CS TR 23- 0057. Professional Services, Steam to Hot Water Conversion and AHU Replacement.	9	Spectra Engineering Ltd.	Yes	No	4	\$91,950	March 2023/ May 15, 2023	Design and Renewal	School Condition Improvement

7	Design and Renewal	JM23-549P Lawrence Park CI TR-23- 0247 Professional Services, Steam to HW Conversion & AHU Replacement.	8	Spectra Engineering Ltd.	Yes	No	4	\$194,500	April 2023/ July 3, 2023	Design and Renewal	School Condition Improvement
8	Design and Renewal	HT23-533P Jarvis CI TR-23-0248. Professional Services, Steam to HW conversion phase 2.Z	10	Spectra Engineering Ltd.	Yes	No	4	\$88,800	April 2023/ June 12, 2023	Design and Renewal	School Condition Improvement
9	Design and Renewal	VK23-538T Diefenbaker ES TR-20- 0273 Chiller Glycol System Flushing & Balancing. Work needed to complete the project in absence of the original Contractor.	15	Carmichael Engineering Ltd.	Yes	No	4	\$52,900	April 2023/ May 2023	Design and Renewal	School Condition Improvement
10	Design and Renewal	DJ23-604P East York CI TR-23-0305 Professional Services, Replacement of fluid cooler, make-up air units and air handling units.	16	Suri & Associates Ltd.	Yes	No	5	\$73,450	April 2023/ July 24, 2023	Design and Renewal	School Condition Improvement
11	Design and Renewal	DK23-600P Mark Garneau CI TR-22- 0827- Professional Services, Replacement of Air Handling Units. Replacement of fluid cooler, make-up air units and air handling units.	11	Spectra Engineering Ltd.	Yes	No	5	\$58,750	March 2023/ May 15, 2023	Design and Renewal	School Condition Improvement
	1			STRUCTUR	AL / BRICK W	ORK					
12	Design and Renewal	HT23- 503T Glenview SPS TR-21- 1222. Replace Exterior Wooden Stairs. Replacement of the south exterior wooden stairs with concrete stairs.	8	Duron Ontario Ltd.	Yes	No	4	\$240,000	February 2023/ Aug 31,2023	Design and Renewal	School Condition Improvement
13	Design and Renewal	JM23-553P Dallington PS TR-21- 1376. Professional Services, Siporex Deck and Roof Replacement at Roof Elevation B1.	13	Engineering Link Incorporated	Yes	No	3	\$79,090	April 2023/ August 15, 2023	Design and Renewal	School Condition Improvement
14	Design and Renewal	JM23-553P Humbercrest PS TR-21- 1381. Professional Services, Siporex Deck and Roof Replacement at Roof Elevation C.	7	Engineering Link Incorporated	Yes	No	3	\$72,850	April 2023/ August 15, 2023	Design and Renewal	School Condition Improvement
15	Design and Renewal	JM23-553P Kingslake PS TR-21- 1383. Professional Services, Siporex Deck and Roof Replacement at Roof Elevation D.	13	Spectra Engineering Ltd.	Yes	No	3	\$63,550	April 2023/ August 15, 2023	Design and Renewal	School Condition Improvement
L	ı	ı		1	1	1	I .	1	1	1	1

16	Design and Renewal	JM23-553P The Elms JMS TR-21- 1393. Professional Services, Siporex Deck and Roof Replacement at Roof Elevations D & D1.	1	Spectra Engineering Ltd.	Yes	No	3	\$66,000	April 2023/ August 15, 2023	Design and Renewal	School Condition Improvement
17	Design and Renewal	JM23-553P Military Trail PS TR-23- 0337 Professional Services, Siporex Deck and Roof Replacement at Roof Elevations A, A1, & C.	19	Engenico Corp.	Yes	No	3	\$83,650	April 2023/ August 15, 2023	Design and Renewal	School Condition Improvement
18	Design and Renewal	JM23-553P George S Henry Academy-Professional Services, Siporex Deck and Roof Replacement at Roof Elevations B3-a, C1, C2, & D1.	14	Engenico Corp.	Yes	No	3	\$67,350	April 2023/ August 15, 2023	Design and Renewal	School Condition Improvement
19	Design and Renewal	JM23-553P Wexford CSA TR-23- 0335 Professional Services, Siporex Deck and Roof Replacement at Roof Elevations E, E2, & E3. Additional Roof Replacement Only at Roof Elevation E.	17	Spectra Engineering Ltd.	Yes	No	3	\$85,350	April 2023/ August 15, 2023	Design and Renewal	School Condition Improvement
20	Design and Renewal	JM23-553P Jarvis CI TR-23-0338 Professional Services, Siporex Deck and Roof Replacement at Roof Elevation F.	10	Engenico Corp.	Yes	No	3	\$57,950	April 2023/ August 15, 2023	Design and Renewal	School Condition Improvement
21	Design and Renewal	MP23-597T Hunter's Glen JPS TR- 22-0602 Roof Replacement and Restoration of Entrance Canopies. Existing roof has exceeded its useful lifespan and requires replacement.	17	Greco Construction	Yes	No	6	\$281,500	April 2023/ September 3, 2023	Design and Renewal	School Condition Improvement
22	Design and Renewal	PCM23-602T Danforth CTI TR 22- 1199 Underground Vault Restoration. Existing underground vault structure deteriorated requiring restoration.	15	Trinity Custom Masonry Limited	Yes	No	7	\$268,033	May 2023/ August 2023	Design and Renewal	School Condition Improvement
				WII	NDOWS						
23	Design and Renewal	PCM23-537T Duke of Connaught PS TR 22-1120. Basement Restoration and Window Replacement. Life span of existing single glaze, wooden frame windows have been exceeded requiring replacement.	15	Trinity Custom Masonry Ltd.	Yes	No	7	\$308,750	June 2023/ August 2023	Design and Renewal	School Condition Improvement
	•										•

24	Design and Renewal	MP23-582P Jesse Ketchum JSPS TR-21-0527 Professional Services, Window Replacement and Structural Remediation.	10	G. Bruce Stratton Architects	Yes	No	4	\$62,888	April 2023/ July 26, 2023	Design and Renewal	School Condition Improvement
	l			ELE	CTRICAL		1	I			
25	Design and Renewal	MP23-535T Cornell JPS TR 22-0502 Fire Alarm System Replacement. Existing fire alarm system is outdated and has surpassed its useful lifespan. Require replacement due to difficult to get replacement parts.	19	Stevens & Black	Yes	No	4	\$307,275	April 2023/ December 30, 2023	Design and Renewal	School Condition Improvement
26	Design and Renewal	MP23-535T Military Trail PS TR 22- 0511 Fire Alarm System Replacement. Existing fire alarm system is outdated and has surpassed its useful lifespan. Require replacement due to difficult to get replacement parts.	19	Stevens & Black	Yes	No	4	\$326,725	April 2023/ December 30, 2023	Design and Renewal	School Condition Improvement
27	Design and Renewal	MP23-535T West Hill PS TR 22- 0518 Fire Alarm System Replacement. Existing fire alarm system is outdated and has surpassed its useful lifespan. Require replacement due to difficult to get replacement parts.	22	Stevens & Black	Yes	No	4	\$194,550	April 2023/ December 30, 2023	Design and Renewal	School Condition Improvement
28	Design and Renewal	DJ23-481T John D Parker JPS TR- 22-1111 Re-installation of Hydro Incoming Underground Duct Banks. Remove the existing Hydro Incoming underground duct banks and provide the new underground duct banks at the proper depth to suit Hydro.	1	Kudlak-Baird Limited	Yes	No	3	\$205,454	February 2023/ July 28, 2023	Design and Renewal	School Condition Improvement
29	Design and Renewal	PCM23-554T York Humber HS TR 21-1708 Integrated PA / Inhouse Phone System Replacement & Fire alarm System Replacement. The existing PA system is obsolete and has surpassed its life span. There is a lack of replacement parts available. Continued maintenance is not feasible.	6	Kertech Electric Inc.	Yes	No	5	\$319,345	April 2023/ August 31, 2023	Design and Renewal	School Condition Improvement
30	Design and Renewal	PCM23-554T York Humber HS TR 21-1797 Integrated PA / Inhouse Phone System Replacement & Fire Alarm System Replacement. Existing	6	Kertech Electric Inc.	Yes	No	5	\$403,075	April 2023/ August 31, 2023	Design and Renewal	School Condition Improvement

		fire alarm system is outdated and has surpassed its useful lifespan. Difficult to get replacement parts for the current system.									
31	Design and Renewal	PCM23-550T Malvern CI TR 22-0538 P.A. & In House Phone System Replacement. The existing system is obsolete and surpassed its life span. There is a lack of replacement parts available. Continued maintenance is not feasible.	16	Alltech Electrical Systems Inc.	Yes	No	5	\$422,000	June 2023/ August, 2023	Design and Renewal	School Condition Improvement
32	Design and Renewal	PCM23-527P Chalkfarm PS TR-21- 1106 Supply & Commission Only of P.A. & In House Phone System. Maintaining existing system is becoming expensive and original parts are obsolete. Requiring a new system to be installed.	4	Baldwin Sound System Ltd.	Yes	No	1	\$55,633	April 2023/ May 31, 2023	Design and Renewal	School Condition Improvement
33	Design and Renewal	PCM23-570P Taylor Creek PS TR-21-1110 Supply & Commission Only of P.A. & In House Phone System. Maintaining existing system is becoming expensive and original parts are obsolete. Requiring a new system to be installed.	18	Baldwin Sound System Ltd.	Yes	No	1	\$58,154	April 2023/ May 31, 2023	Design and Renewal	School Condition Improvement
34	Design and Renewal	PCM23-511T Blantyre PS TR-22- 0525 P.A./In-House Phone System Replacement. Existing system is obsolete & has surpassed its life span. There is a lack of replacement parts available. Continued maintenance is not feasible.	18	Stevens & Black Electrical Contractors Ltd.	Yes	No	4	\$228,725	March 2023/ August 25, 2023	Design and Renewal	School Condition Improvement
35	Design and Renewal	PCM23-511T Thomas L. Wells TR-21-1599 P.A./In-House Phone System Replacement. Existing system is obsolete & has surpassed its life span. There is a lack of replacement parts available. Continued maintenance is not feasible.	22	Stevens & Black Electrical Contractors Ltd.	Yes	No	4	\$256,500	March 2023/ August 25, 2023	Design and Renewal	School Condition Improvement
36	Design and Renewal	JM23-601T Palmerston Ave JPS TR- 22-0542 Integrated PA In-House Phone System Replacement. The existing system is obsolete and has	10	Alltech Electrical Systems Inc.	Yes	No	4	\$286,397	May 2023/ August 25, 2023	Design and Renewal	School Condition Improvement

		surpassed its life span. There is a lack of replacement parts available. Continued maintenance is not feasible.									
37	Design and Renewal	MP23-520T Various Schools Upgrade WiFi Access Point. Installation of new access points including cabling and replacement of existing access points with new.	N/A	Hart-Well Electrical	Yes	No	5	\$87,400	March 2023/ August 30, 2023	Design and Renewal	Site-Funded
38	Design and Renewal	JM23-529T Adam Beck JPS TR-22- 0523 PA & In-House Phone Replacement. The existing system is obsolete and has surpassed its life span. There is a lack of replacement parts available. Continued maintenance is not feasible.	16	Kudlak-Baird (1982) Limited	Yes	No	5	\$229,995	June 2023/ August, 2023	Design and Renewal	School Condition Improvement
39	Design and Renewal	VK23-551T General Mercer JPS TR- 22-0534 Integrated P. A. / In-house Phone System Replacement. The existing system is obsolete and has surpassed its lifespan. There is a lack of replacement parts available. Continued maintenance is not feasible.	9	Kudlak-Baird (1982) Limited	Yes	No	5	\$249,687	April 2023/ August 31, 2023	Design and Renewal	School Condition Improvement
40	Design and Renewal	DJ23-561T Victoria Park ES TR-22- 0517. Fire Alarm System Replacement. Existing fire alarm system is outdated and has surpassed its useful lifespan. Difficult to get replacement parts for the current system.	16	RCN Electric	Yes	No	3	\$113,899	April 2023/ August 20, 2023	Design and Renewal	School Condition Improvement
41	Design and Renewal	DJ23-546T Eastview PS TR-22-0504 Fire Alarm System Replacement. Existing fire alarm system is outdated and has surpassed its useful lifespan. Difficult to get replacement parts for the current system.	19	Black & McDonald Ltd.	Yes	No	4	\$316,400	April 2023/ December 30, 2023	Design and Renewal	School Condition Improvement
42	Design and Renewal	DJ23-546T Scarborough Village PS TR-22-0514 Fire Alarm System Replacement. Existing fire alarm system needs to be updated and has surpassed its useful lifespan. Difficult to get replacement parts for the current system.	19	Black & McDonald Ltd.	Yes	No	4	\$205,800	April 2023/ December 30, 2023	Design and Renewal	School Condition Improvement

43	Design and Renewal	VK23-591T Runnymede JSPS TR-22- 0547 Integrated P.A. and In-house Phone System Replacement. The existing system is obsolete and has surpassed its life span. There is a lack of replacement parts available. Continued maintenance is not feasible.	7	Buxton & Dawe Limited	Yes	No	5	\$345,000	April 2023/ August 31, 2023	Design and Renewal	School Condition Improvement
44	Design and Renewal	MP23-592T Annette JSPS TR-22- 0524 In-house Phone System Replacement. The existing system is obsolete and has surpassed its lifespan. Require replacement.	7	Black & McDonald Ltd.	Yes	No	4	\$270,500	April 2023/ August 31, 2023	Design and Renewal	School Condition Improvement
				BARR	IER FREE			1			
-	Nil Items	-	-	-	-	-	-	-	-	-	-
	Nii Itama				ING LOTS	1		1			
-	Nil Items	-	-	- EIEI D DE	- STORATION	-	-	-	-	-	-
45	Design and Renewal	DK23-485T George B Little PS TR- 22-1108 Asphalt Replacement and addressing Drainage in Junior and JK Areas. Asphalt surfaces have deteriorated beyond regular maintenance. Scope of work includes new concrete curbs, asphalt paving and line painting.	19	Lakeside Contracting Company Ltd.	Yes	No	6	\$284,238	March 2023/ August 31, 2023	Design and Renewal	School Condition Improvement
46	Design and Renewal	VK23-540T Mill Valley JS TR-21-1742 Playground Asphalt Resurfacing. The asphalt paved playgrounds were observed to be aged and worn with alligator cracking and uneven surfaces and has now become a health and safety concern. Scope of work includes asphalt resurfacing, line painting and replacement of worn features.	2	Primo Paving & Construction Ltd.	Yes	No	5	\$361,999	April 2023/ August 31, 2023	Design and Renewal	School Condition Improvement
47	Design and Renewal	DJ23-595T Bendale JPS TR-21-1700 Resurface Play Area and North Parking Lot. The asphalt paved parking lot was observed to be aged and worn with patches. Asphalt paving in the asphalt play area has deteriorated over time (e.g., asphalt resurfacing, replace play equipment and site furnishings, concrete pad for	19	Nortown Paving & Construction Inc.	Yes	No	7	\$453,291	April 2023/ September 3, 2023	Design and Renewal	School Condition Improvement

		garbage bins, fencing and line painting).									
				INTERIOR COMPONE	ENTS / FASCI	A / PAINTIN	IG				
48	Design and Renewal	VK23-516P Jarvis CI TR-22-0296 Professional Services, Waterproof & Upgrades to Basement Areas.	10	Weiss Architecture and Urbanism Ltd.	Yes	No	6	\$110,220	April 2023/ July 31, 2023	Design and Renewal	School Condition Improvement
				OTHER							<u> </u>
49	Occupational Health and Safety/ Design and Renewal	JM23-574SSF Downtown Alternative School. Emergency Abatement Black Water Cleanup.	9	Abbot Environmental Ltd	N/A	N/A	N/A	\$79,500	October 2022/ November 2022	Occupational Health and Safety/ Design and Renewal	Renewal
50	Environmental Compliance	JM23-605SSF Scarlett Heights. Emergency abatement of asbestos- containing materials.	2	The BearStar Inc	N/A	N/A	N/A	\$69,938	December 30, 2022	Environmental Compliance	Renewal
51	Sustainability	DA23-322P Various TDSB Sites. Professional Services to Develop Safe Roof Access Program and Validate Roof Access Safety Survey Checklist.	N/A	Rimkus Consulting Group Canada Inc. (IRC Building Sciences Group)	Yes	No	1	\$65,180	March 2023/ May 2023	Sustainability	Renewal
52	Design and Renewal	JM23-559T Tom Longboat JPS TR-22-0879. Resurface Play Area and Kindergarten Drainage. The asphalt paved playground has aged and worn with alligator cracking and uneven surfaces. The kindergarten space is experiencing drainage issues due to surfaces sloping toward the school. Scope of work includes asphalt resurfacing, line painting, and drainage remediation.	21	Onsite Contracting Inc	Yes	No	6	\$484,017	April 2023/ August 20, 2023	Design and Renewal	School Condition Improvement

APPENDIX B

Facility Services Contracts Requiring Finance, Budget and Enrolment Committee Approval (over \$500,000 and up to \$1,000,000)

#	User/Budget Holder School/Dept.	Products/Services Details	Ward	Recommended Supplier	Low Bid / Highest Score	Object -ions	No. of Bids Rec'd	Total Contract Amount	Projected Start/End Date of Contract	Customer Involvement	Funding Source
				ROOFING		_			_		
-	Nil Items	-	-	-	-	-	-	-	-	-	-
			ı	MECHANICA	<u>\</u> L	ı	ı	T	1	T	T
-	Nil Items	-	-	-	-	-	-	-	-	-	-
_				STRUCTURAL / BRI	CK WORK						
1	Design and Renewal	JM23-536T Malvern CI TR-22-1104 Exterior Wall & Cluster Column Restoration. Structural reinforcement of cluster columns is required to guarantee safe occupancy.	16	Trinity Custom Masonry Limited	Yes	No	5	\$708,000	June 2023/ August, 2023	Design and Renewal	School Condition Improvement
				WINDOWS)					l	
2	Design and Renewal	PCM23-587T Knob Hill PS TR 22- 1000. Window, Door and Sofit Restoration. Original window assembly is deteriorated and beyond its useful life requiring replacement. Existing doors are worn with visible corrosion requiring replacement.	17	Inter-All Ltd.	Yes	No	5	\$837,777	May 2023/ December 31, 2023	Design and Renewal	School Condition Improvement
				ELECTRICA	L						
3	Design and Renewal	DJ23-531T Duke of Connaught TR- 22-0532. PA & Inhouse Phone Replacement. The existing system is obsolete and has surpassed its life span. There is a lack of replacement parts available. Continued maintenance is not feasible.	15	Hart-Well Electrical Company Ltd.	Yes	No	5	\$643,670	June 2023/ August, 2023	Design and Renewal	School Condition Improvement
				BARRIER FR	<u> </u>			<u> </u>		<u> </u>	<u> </u>
_	Nil Items	-	-	-		-	-	-	-	_	-
			<u> </u>	PARKING LO	TS	<u> </u>	<u> </u>	I	1	ı	I

4	Design and Renewal	VK23-494T Amesbury MS TR-20- 0155 Repave Parking Lot. Asphalt surfaces at the parking lot and front of the school have deteriorated beyond regular maintenance. Scope of work includes new concrete curbs, asphalt paving, line painting, signage.	6	Onsite Contracting Inc.	Yes	No	7	\$542,474	May 2023/ August 31, 2024	Design and Renewal	School Condition Improvement
5	Design and Renewal	VK23-526T Harrison PS TR-19-1138 Repave Parking Lot & Play Area. Parking lot paving is deteriorated and requires re-paving. Asphalt play area is deteriorated with several cracking and drainage issues.	11	Kings Valley Paving Inc.	Yes	No	7	\$760,000	May 2023/ August 31, 2024	Design and Renewal	School Condition Improvement
6	Design and Renewal	HT23-491T A Y Jackson SS TR-21- 1057 Parking Lot and Bus Loop Upgrades - Asphalt surfaces have deteriorated beyond regular maintenance. The scope of work includes new concrete curbs, asphalt paving, line painting, signage, lighting, and accessibility upgrades.	13	Ashland Paving Ltd	Yes	No	8	\$708,000	May 2023/ August 25, 2023	Design and Renewal	School Condition Improvement
				FIELD RESTORA	ATION						
7	Design and Renewal	VK23-483T West Hill PS TR-22-1037 Resurface Play Areas & Replace Deteriorated Play Equipment. Playground areas require upgrades to enhance learning environment of students. Improvements include asphalt and replacement of deteriorated site features.	22	DonRos landscape Contractors	Yes	No	5	\$763,130	May 2023/ August 30, 2023	Design and Renewal	School Condition Improvement
8	Design and Renewal	DJ23-501T Bedford Park PS TR-20-0189 Replacement of Brick Paving, Iron Fence and Wood Retaining Wall. The interlocking brick paved walkways at the south play area are uneven and pose a tripping hazard. The wrought iron fence/guard is aged and corroded, while the wood fence on the wood retaining wall is aged and deteriorated.	11	Onsite Contracting Inc.	Yes	No	5	\$545,362	May 2023/ August 31, 2023	Design and Renewal	School Condition Improvement

		JM23-506T Lamberton PS TR-22-									
9	Design and Renewal	O612 Repave Play Area & Replace Deteriorated Play Equipment. The asphalt paved playground was observed to be aged and worn with alligator cracking and uneven surfaces. The unpaved playing surfaces were observed to have barren sections and reportedly poor drainage. Scope includes improvements to site drainage, restoration of deteriorated asphalt paving and play equipment.	4	Pave-1 Construction Ltd	Yes	No	5	\$931,215	May 2023/ August 31, 2023	Design and Renewal	School Condition Improvement
10	Design and Renewal	DK23-496T Yorkwoods PS TR-22- 1038 Resurface Play Areas & Replace Deteriorated Play Equipment. The asphalt paved played areas were observed to be aged and worn with, alligator cracking, uneven surfaces and poor drainage. The unpaved playing surfaces were observed to have barren sections and reportedly poor drainage. Scope of work includes resurfacing unpaved play areas, resurfacing deteriorated asphalt paving and replacing deteriorated play equipment.	4	DonRos Landscape Contractors	Yes	No	6	\$693,615	May 2023/ August 31, 2023	Design and Renewal	School Condition Improvement
11	Design and Renewal	JM23-497T Driftwood PS TR-22-0815 Repave Play Area & Replace Deteriorated Play Equipment. The asphalt paved playground was observed to be aged and worn with alligator cracking and uneven surfaces. The unpaved playing surfaces were observed to have barren sections and poor drainage. Project scope of work includes improvements to site drainage (70,000 sq.ft.), restoration of deteriorated asphalt paving (40,000 sq.ft.) and replacement of deteriorated play equipment.	4	Primo Paving & Construction Ltd.	Yes	No	6	\$884,000	May 2023/ August 31, 2023	Design and Renewal	School Condition Improvement
			IN	ITERIOR COMPONENTS / F	ASCIA / PA	INTING		Γ	Γ	T	
-	Nil Items	-	-	-	-	-	-	-	-	-	-
				OTHER				,			
-	Nil Items	-	-	-	-	-	-	-	-	-	-

APPENDIX C

Facility Services Contracts Requiring Board Approval (contracts over \$1,000,000 and Consulting Services over \$50,000)

#	User/Budget Holder School/Dept.	Products/Services Details	Ward	Recommended Supplier	Low Bid / Highest Score	Object -ions	No. of Bids Rec'd	Total Contract Amount	Projected Start/End Date of Contract	Customer Involvement	Funding Source
			•	ROOFING		•					
1	Design and Renewal	JM23-470T Three Valleys PS TR-21- 1559 Siporex Deck and Roof Replacement Sections C and D. Existing roof has exceeded its useful lifespan and requires replacement.	14	Semple Gooder Roofing Corporation	Yes	No	8	\$2,671,193	May 2023/ August 31, 2023	Design and Renewal	School Condition Improvement
2	Design and Renewal	JM23-479T Taylor Creek PS TR-21- 1394 Siporex Deck & Roof Replacement. Investigation into roof elevations B2 and C revealed the Siporex deck with critical deficiencies requiring replacement. To replace the Siporex deck the roof assembly must be removed and replaced once the new Siporex is installed.	18	Cordeiro Roofing Ltd.	Yes	No	8	\$1,570,000	May 2023/ August 20, 2023	Design and Renewal	School Condition Improvement
3	Design and Renewa <mark>l</mark>	JM23-543T Winchester JSPS TR-22-1328 Roof Replacement Bldg A - A, A1, A2, A3, A4, A5, A6, A7, A8 & Bldg B - A, A1, A2, B, B1, B2, CD1 to 5, DE1 to 11, E, F, F1, DF and Anti-Climb Fence. Existing roof has exceeded its useful lifespan and requires replacement.	10	Semple Gooder Roofing Corporation	Yes	No	9	\$1,423,492	May 2023/ August 31, 2023	Design and Renewal	School Condition Improvement
4	Design and Renewal	DJ23-579T Perth Avenue JPS TR-22- 0051 Siporex Deck (Ba) and Roof (B, Ba, C) Replacement. Existing roof and Siporex roof deck have exceeded their useful lifespan and requires replacement.	9	Triumph Roofing & Sheet Metal Inc.	Yes	No	8	\$3,220,030	May 2023/ August 31, 2023	Design and Renewal	School Condition Improvement
				MECHANICA	\L						
5	Design and Renewal	MP23-548T Frankland CS TR-22- 0299 Air Handlers Replacement. The ventilation system condensing unit is	15	S.I.G. Mechanical Services Ltd.	Yes	No	6	\$1,254,943	May 2023/ August 31, 2024	Design and Renewal	School Condition Improvement

		beyond its useful lifespan and functionality. Require replacement.										
	STRUCTURAL / BRICK WORK											
-	Nil Items	<u>-</u>	-	- WINDOWS	-	-	-	-	-	-	-	
6	Design and Renewal	JM23-486T St Andrew's MS TR-22- 0997 Window and Door Replacement. Original window assembly is deteriorated and beyond its useful life requiring replacement. Existing doors are worn with visible corrosion requiring replacement.	11	Duron Ontario Ltd	Yes	No	2	\$1,303,000	May 2023/ August 31, 2024	Design and Renewal	School Condition Improvement	
7	Design and Renewal	VK23-476T Highland MS TR-22-0811 Window and Door Replacement. Original window assemblies are deteriorated and beyond their useful life requiring replacement. Existing doors are worn with visible corrosion requiring replacement.	13	Duron Ontario Ltd.	Yes	No	6	\$1,389,000	May 2023/ August 25, 2023	Design and Renewal	School Condition Improvement	
8	Design and Renewal	MP23-528T A Y Jackson SS TR-22- 0833 Window and Door Replacement. Original window assemblies are deteriorated and beyond their useful life. Existing doors are worn with visible corrosion. Require replacement.	13	Trinity Custom Masonry Limited	Yes	No	4	\$3,330,000	May 2023/ August 23, 2024	Design and Renewal	School Condition Improvement	
9	Design and Renewal	VK23-547T Oakwood CI TR-22-0910 Window and Door Replacement – Ph. 1. Original window assembly is deteriorated and is beyond its useful life requiring replacement. Existing doors are worn with visible corrosion requiring replacement.	9	Duron Ontario Ltd.	Yes	No	7	\$1,900,500	May 2023/ August 31, 2023	Design and Renewal	School Condition Improvement	
10	Design and Renewal	DK23-505T City Adult Learning Centre TR-21-1126 Window Replacement 7 th Floor. Original window assembly is deteriorated and beyond its useful life requiring replacement.	15	Duron Ontario Ltd.	Yes	No	4	\$1,375,000	May 2023/ August 31, 2023	Design and Renewal	School Condition Improvement	

				ELECTRICA	L						
-	Nil Items	-	-	-	-	-	-	-	-	-	-
	BARRIER FREE										
-	Nil Items	-	-	-	-	-	-	-	-	-	-
	PARKING LOTS										
11	Design and Renewal	Parking Lot and Playground Upgrades. Parking lot asphalt surfaces have deteriorated beyond regular maintenance. Scope of work includes new concrete curbs, asphalt paving, line painting, signage, accessibility upgrades. Playground areas require re-grading and upgrades to improve drainage conditions and learning environment of students. Improvements include soft landscaping, asphalt, walkway, play structures, seating.	12	Onsite Contracting Limited	Yes	No	5	\$1,063,016	May 2023/ August 25, 2023	Design and Renewal	Site Funded
	•			FIELD RESTORA	TION	•		1	1		
12	Design and Renewal	JM23-569T Rosedale JPS TR-22- 0914 Repave Play Area & Replace Deteriorated Playground Equipment. Playground areas require upgrades to enhance learning environment of students. Improvements include asphalt resurfacing, line painting and replacement of playground equipment and worn features.	10	Onsite Contracting Inc	Yes	No	5	\$1,091,311	May 2023/ August 31, 2023	Design and Renewal	School Condition Improvement and Site Funded
13	Design and Renewal	VK23-504T Forest Hill Cl TR-22-0921 Replace Deteriorated Asphalt Paving in Play Areas and Parking Lots. Asphalt play areas, including basketball courts having uneven and cracked surfaces and drainage issues. The asphalt paved parking lots are aged and worn. Outdoor learning and gathering areas at the front of the school are in disrepair and require replacement.	8	Onsite Contracting Inc	Yes	No	5	\$1,281,861	May 2023/ August 31, 2023	Design and Renewal	School Condition Improvement
14	Design and Renewal	DK23-478T Gosford PS TR-22-0911 Repave Play Area and Replace Deteriorated Play Equipment.	4	DonRos Landscape Contractors	Yes	No	5	\$1,089,418	May 2023/ August 31, 2023	Design and Renewal	School Condition Improvement

		Playground areas require upgrades to enhance learning environment of students. Improvements include (e.g., site drainage, asphalt, play structures, etc.)									
15	Design and Renewal	DJ23-513T Gledhill JPS TR-21-1309 School Yard Improvements. School site requires re-grading to improve drainage conditions. Upgrades will improve accessibility to various areas of the school.	16	Lakeside Contracting Company Limited	Yes	No	5	\$1,017,607	June 2023/ August 2023	Design and Renewal	School Condition Improvement/ School Contribution
			11	TERIOR COMPONENTS / F.	ASCIA / PA	INTING					
16	Design and Renewal	JM23-586T Vaughan Road Academy TR-22-1407 Pool Facade Glass Block and Concrete Panel Replacement. TR-22-1377 Replace Ceilings and Interior Finishes in Weight Room and Change Rooms. Upgrades to various interior and exterior components within the north wing of the building that are identified as urgent/high/medium priority for replacement in the 2014 Facility Condition Report.	8	Martinway Contracting Ltd.	Yes	No	3	\$4,761,182	May 2023/ November 30, 2023	Design and Renewal	School Condition Improvement
	OTHER										
-	Nil Items	-	-	-	-	-	-	-	-	-	-

Summary of Select Facilities Contracts

(September 1, 2022 to Present)

-	Project Classification	Total Number of Projects for this Report	Total Number of Projects 2022/23 to date	Total Expenditures for this Report	Total 2022/23 Contract Awards Reported to Date	Current Backlog
1	ROOFING	6	62	\$9,212,815	\$100,852,875	\$ 73,918,032
2	MECHANICAL	10	77	\$2,533,053	\$90,942,241	\$ 1,660,226,066
3	STRUCTURAL / BRICK WORK	12	43	\$2,073,323	\$16,136,291	\$ 146,843,259
4	WINDOWS	8	19	\$10,506,915	\$21,349,389	\$ 73,067,794
5	ELECTRICAL	21	95	\$5,526,184	\$26,395,606	\$ 425,691,172
6	BARRIER FREE	0	0	0	0	-
7	PARKING LOTS	4	20	\$3,073,490	\$9,635,701	\$ 96,192,052
8	FIELD RESTORATION	12	29	\$9,397,047	\$20,134,911	\$ 242,432,336
9	INTERIOR COMPONENTS / FASCIA / PAINTING	2	16	\$4,871,402	\$12,331,755	\$ 931,643,271
10	OTHER (FDK, EL4, and Compliance)	4	15	\$698,635	\$3,018,140	-

-	Project Classification	Total Number of CVRIS Projects for this Report	Total Number of CVRIS Projects to date	Total CVRIS Expenditures for this Report	Total CVRIS Contract Awards Reported to Date
-	COVID Resilience Infrastructure Funding Stream (CVRIS) Projects *	0	13	-	\$ 5,857,555

^{*} Note: these CVRIS values are also reflected in the main Appendix D table above under their appropriate trade category.

Overall Running Total (CVRIS) Projects from April 2021 to Date:	75	Total April 2021 to Date:	\$ 46,095,451
April 2021 to Bate.		Date.	

APPENDIX E

Facilities Services Contract Change Orders Exceeding \$500,000

Nil Items

